


ITEM# 321



QUICK START GUIDE

180 ST+ WELDER (NOT RECOMMENDED FOR ALUMINUM)



TIG WELDING SET-UP

1. **Read user manual**

2. **Select DC TIG process**

TIG Torch Electrode Holder Ground Clamp

** TIG Torch Sold Separately*

3. **Connect TIG torch and ground clamp**

4. **Connect TIG torch lead to gas (100% Argon)**

5. **Adjust amperage per material thickness**

6. **Connect to Input power**

Dedicated Circuit
240VAC - 50A
breaker recommended
or 120VAC - 20A
outlet, 30A breaker

- Generator OK with continuous output $\geq 4,000$ W (120V) or 10,500 W (240V)
- Extension cord: (120V) #12 AWG or #10 AWG (240V) or larger. 25' (8m) or shorter recommended
- Always follow local electrical codes

7. **Use lift arc technique to initiate a welding arc**

ELECTRODE IS ALWAYS ELECTRICALLY HOT WHILE IN TIG MODE



STICK WELDING SET-UP

1. **Select STICK process**

2. **Connect electrode holder and ground clamp according to desired polarity**

Usually DCEP - Electrode Positive

3. **Connect to Input power**

Dedicated Circuit
240VAC - 50A
breaker
recommended or
120VAC - 20A
outlet, 30A breaker

- Generator OK with continuous output $\geq 4,000$ W (120V) or 10,500 W (240V)
- Extension cord: (120V) #12 AWG or #10 AWG (240V) or larger. 25' (8m) or shorter recommended
- Always follow local electrical codes

4. **Adjust amperage per settings chart**


5. Recommended electrodes

Electrode	Diameter		Amperage AMPS	Pulse Recommendations	
	Inches	MM		Hz	% On
E6010 & E6011	3/32	2,4	30-75	3.5-4.2	50-55%
	1/8	3,2	35-125		
	5/32	4,0	80-160		
E6013	1/16	1,6	10-50	>5	>50%
	3/32	2,4	40-90		
	1/8	3,2	50-130		
	5/32	4,0	90-180		
E7014	3/32	2,4	40-90	2-2.4	40-45%
	1/8	3,2	60-130		
	5/32	4,0	90-180		
E7018	3/32	2,4	50-80	5.5-6.5	50-90%
	1/8	3,2	80-160		
	5/32	4,0	90-180		

**Performance may vary by brand*



QUESTIONS OR TROUBLE? Contact Forney Industries at 1-800-521-6038
 customerservice@forneyind.com • askforney.com • forneyind.com




ITEM# 321



TROUBLESHOOTING TIPS

180 ST+ WELDER (NOT RECOMMENDED FOR ALUMINUM)



TROUBLESHOOTING TIPS

Aluminum welding



- Not recommended for this machine.
- Output is DC only which is not suitable for TIG welding aluminum.

Workpiece grounding



Connect ground clamp to clean, bare metal. No rust, paint or other coatings. Attach the ground clamp directly to the workpiece if you are experiencing issues.

Fault Codes



Duty-cycle exceeded or insufficient air flow. Allow machine to cool. Ensure vents are clear of obstacles. See manual.



Incorrect input power. Verify machine is plugged into an appropriate power source. Use proper extension cords. See manual.



Electrode is shorted or stuck to workpiece. Separate the electrode or tungsten from the workpiece and fault will clear. See manual.

Frequently tripping circuit breaker or exceeding duty cycle


Use 5/32" diameter electrodes or smaller. Some 5/32" will draw too much amperage (stick).

Trying to weld single pass on material larger than 3/8" thick is not possible with this machine. Multi-pass recommended for thicker materials.

Welding machine should be the only thing plugged into the circuit.

Low weld output or poor fusion


- Usually due to low input power.
- Pulse settings may be causing poor fusion. Increase the Pulse (% On) setting or set the Pulse (Hz) to 2 Hz or higher.
- Welder should be only thing plugged into circuit.
- Avoid using extension cords. If one must be used, it must be #12 AWG (120V) or #10 AWG (240V) or larger; 25' (8m) or shorter.
- Generators must be 10,500 W (240 V) or 4,000 W (120 V) continuous output and not have a low-idle function (or have it disabled).




PULSE WELDING TIPS

Why Pulse Weld?


Pulse welding alternates between the set output amperage and a reduced amperage. This allows the weld puddle to cool and solidify during each low amp cycle. This has many benefits such as:



Out of Position




Thin Material
Down to 16 gauge




Visually Appealing

How to set up Pulse Welding:

PULSE (Hz) Set pulse frequency from 0.1 up to 10 Hz changes how fast the arc pulses



PULSE (% On) Set pulse % On from 10 to 90. Changes what percent of the pulse is at the user set output amperage



Expert-Tech Tips:

- A higher frequency creates a focused puddle and a tight ripple bead pattern. A lower frequency creates a broader puddle and unique ripple bead pattern.
- A higher setting for Pulse (% On) will increase penetration while a lower value is better for thin material.
- Keep Hz over 2 and % On over 40 when stick welding to avoid arc loss and sticking.
- Read the manual for more information.



QUESTIONS OR TROUBLE? Contact Forney Industries at 1-800-521-6038
customerservice@forneyind.com • askforney.com • forneyind.com

EN_V1